

SEE PG 82

PROBLEMS WITH AXLE/DAMPER CONNECTORS

① RIGHT SIDE NEEDED NEW CENTRAL STUD;
THEN NEEDED END CAP RE-TAPPED, AND STUD
INSERTED, SWAGED, PEENED.

② RENOVATE PLUGGED/RUSTED PARTS, BOTH SIDES.

