


FUEL TANK SUPPORT HDW

79



* RE-INSTALL W/REG HEX NUT - NO "HOLE" IN STUD ON FUEL TANK SO NO REASON FOR CASTLE NUT.

** THERE WERE NO $\frac{1}{4}$ -26 x $\frac{3}{4}$ BOLTS WITH HOLES FOR COTTER PINS IN MY PARTS
CAUS SO USED REG BOLTS & NUTS.